

AC SOURCES SERVICE CO., LTD.

201, Lixin building, Jinyuhaoting, Fuyong, Baoan Dis. Shenzhen, China

Tel: +86 (0)755 27380246 Email: ac.sources@126.com szacsources@gmail.com

INSPECTION REPORT

| | | | |
|----------------------------|-------------------------------------|---------------|------------------|
| Product Description | Big powder brush | Date | Apr. 10, 2009 |
| Supplier | LANFUNG COSMETIC PRODUCTS CO., LTD. | Po No. | IE0908, IE0908-1 |

Inspection method applied:

ANSI/ASQ Z1.4 2003, P-INSP-WI-HL117, Single sampling plans for normal inspection or L-II

Acceptable Quality Level (AQL) for: **Critical:** 0 **Major:** 2.5 **Minor:** 4.0

Sample size inspected: 315pcs

Sample selected from carton numbers:

Checked 5CTNS, supplier not marked the CTN NOS when inspected.

OVERALL INSPECTION CONCLUSION:

PASS ● FAIL ○ PENDING ○

INSPECTION SUMMARY:

| | Pass | Fail | Pending | N/A | Remark |
|------------------------------------|------|------|---------|-----|--------|
| 1. Quantity | Pass | | | | |
| 2. Style, Material, Color | Pass | | | | |
| 3. Workmanship/Appearance/Function | Pass | | | | |
| 4. Packing | Pass | | | | |
| 5. Marking/label/Barcode | Pass | | | | |
| 6. Data measurement/field tests | Pass | | | | |

1. Quantity:

| P.O. No. | Order Q'ty | Inspection Q'ty | | Number of Cartons | |
|------------------|---------------|-----------------|------------|-------------------|------------|
| | | Packed | Not Packed | Packed | Not Packed |
| IE0908, IE0908-1 | 15,000pcs | 14,700pcs | 300pc | 49ctns | 1ctn |
| | Total: | 14,700pcs | 300pc | 49ctns | 1ctn |

2. Style, Material, Color:

| | Pass | Fail | N/A | Pending |
|--------------|------|------|-----|---------|
| 2.1 Style | Pass | | | |
| 2.2 Material | Pass | | | |
| 2.3 Color | Pass | | | |

Inspector: Dillon Supplier: _____ Approved By: _____

3. Workmanship Appearance/Function:

| Defect description | Critical | Major | | Minor | |
|--|----------|-------|-------|-------|-------|
| | | Q'ty | % | Q'ty | % |
| 3.1: there is loose between AL. tube and handle, can be moved, but can not be taken off. | | 5pcs | 1.60% | | |
| 3.2: scathed on surface | | | | 6pcs | 1.90% |
| 3.3: lack some of hair | | 1pc | 0.32% | | |
| 3.4: dirty on PVC bag | | | | 2pcs | 0.63% |
| Total defectives: | | 6pcs | 1.92% | 8pcs | 2.53% |
| Maximum allowed: | | 14pcs | | 21pcs | |

Requested AQL Critical defective maximum allowed: 0 Within AQL ● Beyond AQL ○
 Major defective maximum allowed: 14 Within AQL ● Beyond AQL ○
 Minor defective maximum allowed: 21 Within AQL ● Beyond AQL ○

4. Packing

| | Pass | Fail | N/A | Pending |
|------------------------|------|------|-----|---------|
| 4.1 Individual packing | Pass | | | |
| 4.2 Inner packing | Pass | | | |
| 4.3 Export packing | Pass | | | |
| Remarks | | | | |

5. Marking/label/Barcode

| | Pass | Fail | N/A | Pending |
|----------------------------|------|------|-----|---------|
| 5.1 Shipping Mark | Pass | | | |
| 5.2 Side Mark | Pass | | | |
| 5.3 Barcode | | | N/A | |
| 5.4 Label/Tag/Paper card | | | N/A | |
| 5.5 Logo print on products | Pass | | | |
| 5.6 Poly bag printing | Pass | | | |
| 5.7 Warning Label | | | N/A | |
| Remarks | | | | |

6. Data measurement/field tests:

6.1 Size

Size of Sample:

Product size:

6.2 Function Test:






7. Informative Remark: N/A

N/A

Inspector: Dillon Supplier: _____ Approved By: _____

8. Related photos:

| | |
|--|--|
|  |  |
| <p>Loose 1</p> | <p>Loose 2</p> |
|  |  |
| <p>Scathed on surface</p> | <p>Lack of some hair</p> |
|  |  |
| <p>Dirty on PVC bag</p> | <p>Outer packing</p> |
|  |  |
| <p>Inner packing</p> | <p>Individual packing</p> |

| | |
|--|--|
|  |  |
| <p>Logo printing on products</p> | <p>Mass products 1</p> |
|  |  |
| <p>Mass products 2</p> | <p>Printing on PVC bag</p> |
|  |  |
| <p>Size 1</p> | <p>Size 2</p> |
|  |  |
| <p>Shipping mark</p> | <p>Side mark 1</p> |



Side mark 2

Inspector: Dillon Supplier: _____ Approved By: _____